

Система обозначения CERATIZIT

Фрезы

C 211 . 25 . R . 05 - 07 - A20 - 50 - 225

1 2 3 4 5 6 7 8 9

C 211 . 25 . R . 02 K4 - 11 - B - 50

1 2 3 4 5 10 6 7 8

A 273 . 80 . R . 10 A 10 - 06

1 2 3 4 5 11 12 6


M HPC . 50 . R . 05 - 12 - H63A - 80

1 2 3 4 5 6 7 9


1

Хвостовик


C с хвостовиком




G с резьбой



M Цельная



A с отверстием



2

Система

MaxiMill 211

·
·
·


3

Диаметр


Пазовые



Торцовые




С круглыми вставками



4

Резание

R



L

