


## СТЕ ПАС



L [mm]	W [mm]	T [mm]	α [°]	MG18
50	60	3.18	45	11471514
60	38	3.18	45	11471515
60	50	3.18	45	11471518
60	60	3.18	45	11471520
70	38	3.18	45	11471522
70	50	3.18	45	11471524
70	60	3.18	45	11471527
80	38	3.18	45	11471531
80	50	3.18	45	11471534
80	60	3.18	45	11471537
90	38	3.18	45	11471541
90	50	3.18	45	11471542
90	60	3.18	45	11471545
100	38	3.18	45	11471670
100	50	3.18	45	11471675
100	60	3.18	45	11471676
110	38	3.18	45	11471683
110	50	3.18	45	11471684
110	60	3.18	45	11471685
120	38	3.18	45	11471687
120	50	3.18	45	11471688
120	60	3.18	45	11471689
130	38	3.18	45	11471690
130	50	3.18	45	11471691
130	60	3.18	45	11471692
150	38	3.18	45	11471693
150	50	3.18	45	11471695
150	60	3.18	45	11471698
170	38	3.18	45	11471699