

Spindle nose tooling

Overview

Rotating spindle nose tools		DIN69871	MAS-BT	HSK-A	PSC	UTS	
	Weldon adapters	#R01#	#R02#	#R03#	#R04#	#R05#	
	Whistle Notch adapters	#R07#	#R08#	#R09#	#R10#	#R11#	
	Shrink fit adapters	#R13#	#R14#	#R15#	#R16#		
	Hydraulic expansion chucks	#R19#	#R20#	#R21#	#R22#		
	Collet chucks type ER	#R25#	#R26#	#R27#	#R28#	#R29#	
	Collet chucks type ER-D	#R31#	#R32#				
	Collet chucks type OZ	#R37#	#R38#				
	Combination shell mill adapters	#R43#	#R44#		#R46#		
	Shell mill adapters, centre bolt	#R49#	#R50#	#R51#		#R53#	
	Adapters for threaded shank milling cutters			#R57#	#R58#		
	Shell mill adapters, 4 bolts	#R61#	#R62#				
	Morse taper adapters with tang	#R67#	#R68#	#R69#			
	Morse taper adapters with thread	#R73#	#R74#		#R76#		
	PSC adapters			#R81#			
	Test bars	#R85#	#R86#	#R87#	#R88#		