





MAS-BT

Morse taper adapters with tang / Morse taper adapters with thread



Type, description	d ₁ Morse taper [MK]	l ₁ [mm]	d _A [mm]	D [mm]
MAS-BT-AD40.KH.MK1.50.V	1	50	40	25
MAS-BT-AD40.KH.MK2.50.V	2	50	40	32
MAS-BT-AD40.KH.MK3.70.V	3	70	40	40
MAS-BT-AD40.KH.MK4.95.V	4	95	40	48
MAS-BT-AD50.KH.MK1.45.V	1	45	50	25
MAS-BT-AD50.KH.MK2.60.V	2	60	50	32
MAS-BT-AD50.KH.MK4.95.V	4	95	50	48
MAS-BT-AD50.KH.MK5.105.V	5	105	50	63



Type, description	d ₁ Morse taper [MK]	l ₁ [mm]	d _A [mm]	D [mm]	E#
MAS-BT-A40-MK3C-70-V	3	70	40	40	E01
MAS-BT-A40-MK4C-95-V	4	95	40	48	E02
MAS-BT-A50-MK1C-45-V	1	45	50	25	E03
MAS-BT-A50-MK2C-60-V	2	60	50	32	E04
MAS-BT-A50-MK3C-65-V	3	65	50	40	E01
MAS-BT-A50-MK4C-95-V	4	95	50	48	E02
MAS-BT-A50-MK5C-118-V	5	118	50	63	E05

E01	8335901700	8395003000	8395001800	8395026900
E02	8335902300	8395003100	8395001900	8395027000
E03	8335902000	8395003100	8395026000	8395026600
E04	8335902000	8395003100	8395001700	8395026800
E05	8335903300	8395003100	8395026200	8395027100

