






PSC

Weldon adapters



Type, description	d ₁ [mm]	l ₁ [mm]	d _A [mm]	D [mm]	
PSC50-WE06-50	6	50	50	25	E01
PSC50-WE08-50	8	50	50	28	E02
PSC50-WE10-55	10	55	50	35	E02
PSC50-WE12-60	12	60	50	42	E03
PSC50-WE14-60	14	60	50	44	E03
PSC50-WE16-60	16	60	50	48	E04
PSC50-WE18-60	18	60	50	50	E05
PSC50-WE20-60	20	60	50	52	E06
PSC50-WE25-80	25	80	50	65	E05
PSC63-WE06-55	6	55	63	25	E01
PSC63-WE08-55	8	55	63	28	E02
PSC63-WE10-60	10	60	63	35	E02
PSC63-WE12-60	12	60	63	42	E03
PSC63-WE14-60	14	60	63	44	E03
PSC63-WE16-65	16	65	63	48	E04
PSC63-WE18-65	18	65	63	50	E05
PSC63-WE20-65	20	65	63	52	E06
PSC63-WE25-80	25	80	63	65	E05
PSC63-WE32-90	32	90	63	72	E06
PSC63-WE40-100	40	100	63	80	E06

	
E01	6295001000
E02	6295001200
E03	6295001600
E04	6295002000
E05	6295002500
E06	6295003200

