


3

Selection of the tool

The product page shows the cutter body range including the main dimensions and information on the types of inserts

- 1 Possible applications
- 2 The main dimensions
- 3 Insert reference
- 4 Spare parts
- 5 Spare parts overview
- 6 Reference regarding further information




4

Selection of the insert

After choosing the tool the insert is selected including chip groove and cutting material

- 1 Chip grooves
- 2 Possible cutting materials
- 3 The main dimensions
- 4 Reference regarding further information



5

Starting parameters

In the last phase it is possible to determine the starting parameters for feed, depth of cut and cutting speed for the respective milling cutter

